

# Inspection Photos

July 19, 2022

Operator: Beeman Oil & Gas Inc- #7125

Location ID: 424711

Location Name: Dawson Creek /1-25

Inspection Document #: 702800461

Routt County, CO

SENW Section 25 T6N R88W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Dawson Creek /1-25  
Location ID: 424711



**Photo 1.** Photo taken from the Location entrance shows an overview of the western portion of the Location.



**Photo 2.** Photo taken from the Location entrance shows an overview of the eastern portion of the Location. Photo shows a portion of the pad not necessary for production operations where interim reclamation is required.



Inspection Photos  
Location Name: Dawson Creek /1-25  
Location ID: 424711



**Photo 3.** Photo taken from the east of the Location shows areas at the east and southeast of the pad which do not appear necessary for production operations where interim reclamation has not been performed.





Inspection Photos  
Location Name: Dawson Creek /1-25  
Location ID: 424711



**Photo 4.** Photo taken from the southeast of the Location shows an example of bull thistle, a CO List B Noxious Weed found throughout the Location.



**Photo 5.** Photo taken from the northeast of the Location shows whitetop, a CO List B Noxious Weed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800461



Inspection Photos  
Location Name: Dawson Creek /1-25  
Location ID: 424711



**Photo 6.** Photo taken from the northeast of the Location shows an example of houndstongue, a CO List B Noxious Weed found throughout the Location.



**Photo 7.** Photo taken from the northwest of the Location shows an example of Canada thistle, a CO List B Noxious Weed found throughout the Location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800461



Inspection Photos  
Location Name: Dawson Creek /1-25  
Location ID: 424711



7/19/22  
+40.450726,-107.213413  
50° NE

**Photo 8.** Photo taken from the north of the Location shows the working pad area is overgrown with vegetation, including around production equipment.



7/19/22  
+40.448563,-107.211749  
261° W

**Photo 9.** Photo taken from the Location access road shows the road is overgrown.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800461



Inspection Photos  
Location Name: Dawson Creek /1-25  
Location ID: 424711



**Photo 10.** Photo taken from the north of the Location shows fluid dripping from production equipment into an inadequate container. Impacted/stained soils were present beneath the container.



**Photo 11.** Photo taken from the well area shows impacted soils around the wellhead.





Inspection Photos  
Location Name: Dawson Creek /1-25  
Location ID: 424711



**Photo 12.** Photo shows a methanol tank adjacent to the well with missing/insufficient wildlife protection BMPs on the secondary containment stock tank.



**Photo 13.** Photo taken adjacent to the well shows unused/unnecessary equipment stored on Location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800461