

Inspection Photos

July 19, 2022

Operator: Beeman Oil & Gas Inc- #7125

Location ID: 434520

Location Name: Dill Gulch /1-22

Inspection Document #: 702800463

Routt County, CO

NWSW Section 22 T6N R88W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Dill Gulch /1-22
Location ID: 434520



Photo 1. Photo taken from the Location entrance shows an overview of the western portion of the Location.



Photo 2. Photo taken from the Location entrance shows an overview of the center of the Location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800463

Inspection Photos
Location Name: Dill Gulch /1-22
Location ID: 434520



Photo 3. Photo taken from the Location entrance shows an overview of the southern portion of the Location which does not appear necessary for production operations. Interim reclamation has not been performed.



Photo 4. Photo taken from the north of the Location shows the eastern portion of the Location which does not appear necessary for production operations. Interim reclamation has not been performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800463

Inspection Photos
Location Name: Dill Gulch /1-22
Location ID: 434520



Photo 5. Photo taken from the center of the Location shows an example of Dalmatian toadflax, a CO List B Noxious Weed found throughout the Location.



Photo 6. Photo taken from the southeast of the Location shows an example of musk thistle, a CO List B Noxious Weed found throughout the Location.

Inspection Photos
Location Name: Dill Gulch /1-22
Location ID: 434520



Photo 7. Photo taken from the northwest of the Location shows an example of Canada thistle, a CO List B Noxious Weed found throughout the Location. Photo also shows the working pad area is overgrown.



Photo 8. Photos taken from the well area shows unused equipment and the Location is overgrown, including around production equipment.



Inspection Photos
Location Name: Dill Gulch /1-22
Location ID: 434520



Photo 9. Photo taken from the tank battery at the west of the Location shows the northernmost tank appears to have spilled from the top of the tank. Impacted soils are present within secondary containment.




Photo 10. Refer to Photo 9 comment.