

Inspection Photos
Location Name: Waag Middle SENW Pad #1
Location ID: 439215



Photo 1: Wellhead Sign




Photo 2: Stained soil

Inspection Photos
Location Name: Waag Middle SENW Pad #1
Location ID: 439215



Photo 3: Wellhead Sign



Photo 4: Stained soil

Inspection Photos
Location Name: Waag Middle SENW Pad #1
Location ID: 439215



Photo 5: Unused equipment



Photo 6: Unused equipment