

# Inspection Photos and Issue Report

7/19/2022

Operator: LARAMIE ENERGY LLC # 10433

Location #312452

Mesa County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: LARAMIE ENERGY LLC # 10433  
Location #312452



**Photo 1:** Photo taken from the Location. Photo shows vegetative establishment throughout the Location is predominantly a Noxious Weeds (brown vegetation, Jointed Goatgrass). Ongoing noxious weed monitoring/management has been inadequate; weeds have established throughout the majority of the Location, creating an invasive monoculture outcompeting desirable plant establishment; location is not progressing towards an 80% desirable perennial revegetation standard.

Inspection Photos  
Operator Name: LARAMIE ENERGY LLC # 10433  
Location #312452



**Photo 2:** Photos show Jointed Goatgrass establishment on the Location.