

Inspection Photos and Issue Report

7/19/2022

Operator: LARAMIE ENERGY LLC # 10433

Location #312512

Mesa County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location #312512



Photo 1: Photos 1-2 taken from the southwestern end of the Location. Photos provide an overview of the Location from northwest, north, northeast to east. Additional reclamation work has been conducted, however desirable perennial plant germination does not appear uniform; vegetation in photos are predominantly annual wheat/rye grasses, noxious weeds (Jointed Goatgrass) or other Undesirable Plant Species such as Kochia and Salsola.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location #312512



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location #312512



Photo 3: Photos examples showing Jointed Goatgrass establishment on the Location. Ongoing noxious weed monitoring/management has been inadequate. Desirable plant germination was not evident, or poor, on areas of the location with high densities of noxious weeds, and/or annual wheat and rye grasses.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location #312512



Photo 4: Photos show the access road leading to the Location. Brown vegetation observed in photos is Jointed Goatgrass. Gravel observed remaining at the access road. Photo also shows compaction alleviation of the access road does not appear to have been conducted in accordance with 1004 requirements; compaction issues evident.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location #312512



Photo 5: Photo shows Jointed Goatgrass on access road.

