

Inspection Photos and Issue Report

7/19/2022

Operator: LARAMIE ENERGY LLC # 10433

Location #334552

Mesa County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location #334552



July 19, 2022



July 19, 2022

Photo 1: Photos provide an overview of the Location.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location #334552



July 19, 2022



July 19, 2022

Photo 2: Photos example of other interim areas of the Location; vegetation appears to meet 1003 standards.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location #334552



July 19, 2022



July 19, 2022

Photo 3: Photos examples showing noxious weeds (bindweed) establishing on the production and interim areas of the Location.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location #334552



Photo 4: Well marker for the Coury 18-2 well. Marker does not comport with monument requirements, however, marker is located within a string of active wells, does not appear to be interfering with production activities, has been fenced off and not an apparent safety issue.