

Inspection Photos

Jul 19, 2022

Operator: Antelope Energy Company LLC - #3250

Location ID: 316746

Location Name: State-66N89W /15NWNE

Inspection Document #: 702800478

Routt County, CO

NWNE Section 15 T6N R89W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: State-66N89W /15NWNE
Location ID: 316746



Photo 1. Photo taken from the west of the Location shows the access road. Perennial grass is failing to establish in the tracks.



Photo 2. Photo taken from the south shows an overview of the Location.



Inspection Photos
Location Name: State-66N89W /15NWNE
Location ID: 316746



Photo 3. Photo taken from the south shows the vegetation community on Location. Light green vegetation is desirable perennial grasses. Dark green, brown and red vegetation is undesirable plant species and noxious weeds.



Photo 4. Photo taken from the east shows the vegetation community on Location. Note large patches of bare ground. Vegetation establishment is not uniform.



Inspection Photos

Location Name: State-66N89W /15NWNE

Location ID: 316746



Photo 5. Photo taken from the center of the Location shows areas dominated by cheatgrass (List C Noxious Weed).



Photo 6. Photo taken from the southwest shows areas dominated by kochia (undesirable plant species) and cheatgrass (List C Noxious Weed).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800478

Inspection Photos
Location Name: State-66N89W /15NWNE
Location ID: 316746



Photo 7. Photo taken from the northeast shows Canada thistle (List B Noxious Weed).



Photo 8. Photo taken from the southwest of the Location shows a t-post remaining on Location (equipment/debris).

Inspection Photos

Location Name: State-66N89W /15NWNE

Location ID: 316746



Photo 9. Photo taken from the east of the Location shows where perennial grasses have failed to establish. Bare and exposed soil dominates. Water flow patterns are evident, indicating soil erosion. Note also the wooden post left on Location (equipment/debris)



Photo 10. Refer to Photo 9 comment.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800478

Inspection Photos
Location Name: State-66N89W /15NWNE
Location ID: 316746



Photo 11. Photo taken from to the south of the Location shows reference area vegetation.