

Taproot. ER for produced water at the Boomslang Pad near Briggsdale, CO.  
EWI Project #212500. A1.

**Photo: 1**

**Description:**

Initial site conditions at the Boomslang Pad.



**Photo: 2**

**Description:**

Initial site conditions at the Boomslang Pad.



Taproot. ER for produced water at the Boomslang Pad near Briggsdale, CO.  
EWI Project #212500. A1.

**Photo: 3**

**Description:**

Initial site conditions at the Boomslang Pad.



**Photo: 4**

**Description:**

A view where the line break occurred.





Taproot. ER for produced water at the Boomslang Pad near Briggsdale, CO.  
EWI Project #212500. A1.

**Photo: 5**

**Description:**

A view looking North of the collection area/retention pond impacted with produced water.



**Photo: 6**

**Description:**

EWI vacuum truck removing liquids from the pond.



Taproot. ER for produced water at the Boomslang Pad near Briggsdale, CO.  
EWI Project #212500. A1.

**Photo: 7**

**Description:**

Surface scrape of shallow impacted soil at the Boomslang Pad.



**Photo: 8**

**Description:**

The hydro-vac excavating and finding the line break.





Taproot. ER for produced water at the Boomslang Pad near Briggsdale, CO.  
EWI Project #212500. A1.

**Photo: 9**

**Description:**

Excavator onsite to excavate impacted soil.



**Photo: 10**

**Description:**

Line break discovered.



Taproot. ER for produced water at the Boomslang Pad near Briggsdale, CO.  
EWI Project #212500. A1.

**Photo: 11**

**Description:**

Retention pond looking south prior to excavation. Also shown is the shallow excavation of soil within the narrow drainage leading to the retention pond.



**Photo: 12**

**Description:**

Final extents of main excavation, looking east.





Taproot. ER for produced water at the Boomslang Pad near Briggsdale, CO.  
EWI Project #212500. A1.

|  |   |
|--|---|
| <p><b>Photo: 13</b></p> <p><b>Description:</b></p> <p>Final extents of retention pond excavation. 2-4' beneath initial retention pond extents.</p> |   |
| <p><b>Photo: 14</b></p> <p><b>Description:</b></p> <p>Final confirmation samples following excavation on 4/27/22.</p>                              |  |