

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOE-66S95W /21NESW

Location ID: 335256



Photo #7212 from entrance to location.



Photo #7213 from entrance to location.

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOE-66S95W /21NESW

Location ID: 335256



Photo #7214 from entrance to location.



Photo #7215 Multiple places with unused equipment.

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOE-66S95W /21NESW

Location ID: 335256



**Photo #7216 Multiple places with unused equipment.**



**Photo #7219 Multiple places with unused equipment.**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOE-66S95W /21NESW

Location ID: 335256



**Photo #7220 Multiple places with unused equipment.**