

Sparks B1 & B3

Date completed 7/19/2022

Document number 702500130

Remove impacted soil from both wellheads



Remove old pump jack weight

Repair pad at entrance to location and slope to allow future drainage



Repair south and east side of location to allow good drainage from hillside

