

Inspection Photos

API: 125-06935

Operator: PETRON DEVELOPMENT COMPANY

Inspection Date: 7/21/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 125-06935 | Date: 7/21/2022

Inspection Photos



Photo 1. Facing east at the abandoned well site. The crop field is currently fallow this year. It was previously observed the well site may not have established sufficient crop cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-06935 | Date: 7/21/2022

Inspection Photos



Photo 2. Facing west at the abandoned well site. The crop field is currently fallow this year. It was previously observed the well site may not have established sufficient crop cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-06935 | Date: 7/21/2022

Inspection Photos



Photo 3. 2016 Aerial image shows the area at the well site which appears to have insufficient crop cover shown by the light area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-06935 | Date: 7/21/2022