

Final Reclamation Inspection

June 21st, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 302170

Inspection Document #: 701900424

NENE Section 31 T7N R63W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Zahourek 41-31
Location ID: 302170



Photo 1. 2020 aerial imagery of the well pad (north is up). Note: tank battery, highlighted in blue, is associated with the Zahourek 42-31 well API #123-27289.

Inspection Photos
Location Name: Zahourek 41-31
Location ID: 302170



Photo 2. Overview photo of the well pad taken at ground level from the southern edge looking north. Note: well pad and surrounding area have been hydro mulch with no evidence of vegetation growth.

Inspection Photos
Location Name: Zahourek 41-31
Location ID: 302170



Photo 3. Cardinal photos taken from the middle of the well pad. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Zahourek 41-31
Location ID: 302170



Photo 4. Cardinal photos taken from the middle of the tank battery. Left photo facing south, right photo facing west. Note: well pad shows minimal vegetation establishment and is dominated by field bindweed (a List C Colorado noxious weed species).