

Inspection Photos

API: 125-07044

Operator: PRIME OPERATING COMPANY

Inspection Date: 7/20/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 125-07044 | Date: 7/20/2022

Inspection Photos



Photo 1. Facing north along the former access road which has revegetated.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-07044 | Date: 7/20/2022

Inspection Photos



Photo 2. Facing north toward the location. There is a t-post and marker that remains and needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-07044 | Date: 7/20/2022

Inspection Photos



Photo 3. Facing south at the location. There are mostly undesirable weeds (Kochia) on a 15'x15' area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-07044 | Date: 7/20/2022

Inspection Photos



Photo 4. View of groundcover at the center of the location shows mostly undesirable weeds (Kochia) on a 15'x15' area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-07044 | Date: 7/20/2022

Inspection Photos



Photo 5. Facing south at the surrounding undisturbed pasture.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-07044 | Date: 7/20/2022