

Inspection Photos
Location Name: NCLP PC AA /08-07D
Location #: 332986



Photo #1
NCLP PC AA /08-07D pad Wellsites
3: Temporarily Abandoned | TA
North → South



Photo #2
NCLP PC AA 08-08D (05-123-32548) Wellsite
Temporarily Abandoned | TA

Inspection Photos
Location Name: NCLP PC AA /08-07D
Location #: 332986



Photo #3

NCLP PC AA 08-07D (05-123-32546) Wellsite
Temporarily Abandoned | TA



Photo #4

New Cache 8-24 (05-123-26868) Wellsite
Temporarily Abandoned | TA

Inspection Photos
Location Name: NCLP PC AA /08-07D
Location #: 332986



Photo #5
New Cache 8-24,
NCLP PC AA 08-02D, 08-03D, 08-07D,
08-08D, 08-18D, 08-19 Battery site
Abandoned: ALL Equipment removed