

**Inspection Photos**  
**Location Name: Schumaker 32-6 13-3**  
**Location ID: 320906**



**IMG 01**  
**Well sign**



**IMG 02**  
**Location overview**



**IMG 03**

**Impacted material**



**IMG 04**

**Signs deteriorating**