

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

07/26/2022

Submitted Date:

07/26/2022

Document Number:

693507574

FIELD INSPECTION FORM

Loc ID 331527	Inspector Name: Silver, Randy	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 21 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested																																																																																																																																																										
Operator Information: OGCC Operator Number: 10633 Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC Address: 1801 CALIFORNIA STREET #2500 City: DENVER State: CO Zip: 80202				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE																																																																																																																																																										
Contact Information: <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> <tr> <td>,</td> <td></td> <td>Cogcc.inspections@crestone pr.com</td> <td>ALL INSPECTIONS</td> </tr> </table>							Contact Name	Phone	Email	Comment	,		Cogcc.inspections@crestone pr.com	ALL INSPECTIONS																																																																																																																																																
Contact Name	Phone	Email	Comment																																																																																																																																																											
,		Cogcc.inspections@crestone pr.com	ALL INSPECTIONS																																																																																																																																																											
Inspected Facilities: <table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> </thead> <tbody> <tr><td>426712</td><td>WELL</td><td>PR</td><td>08/01/2019</td><td>OW</td><td>123-34764</td><td>STELLING 3A-4H</td><td>PR</td></tr> <tr><td>428575</td><td>WELL</td><td>PR</td><td>02/01/2019</td><td>OW</td><td>123-35413</td><td>STELLING 3B-4H</td><td>PR</td></tr> <tr><td>454437</td><td>WELL</td><td>PR</td><td>10/29/2018</td><td>OW</td><td>123-46556</td><td>Ruegge 3D-4H-N165</td><td>PR</td></tr> <tr><td>454438</td><td>WELL</td><td>SI</td><td>05/01/2022</td><td>OW</td><td>123-46557</td><td>Ruegge 3P-4H-N165</td><td>SI</td></tr> <tr><td>454439</td><td>WELL</td><td>PR</td><td>11/01/2018</td><td>OW</td><td>123-46558</td><td>Ruegge 3H-4H-N165</td><td>PR</td></tr> <tr><td>454440</td><td>WELL</td><td>PR</td><td>10/27/2018</td><td>OW</td><td>123-46559</td><td>Ruegge 3I-4H-N165</td><td>PR</td></tr> <tr><td>454441</td><td>WELL</td><td>PR</td><td>10/11/2018</td><td>OW</td><td>123-46560</td><td>Ruegge 3Q-4H-N165</td><td>PR</td></tr> <tr><td>454442</td><td>WELL</td><td>PR</td><td>10/30/2018</td><td>OW</td><td>123-46561</td><td>Ruegge 3L-4H-N165</td><td>PR</td></tr> <tr><td>454443</td><td>WELL</td><td>PR</td><td>11/01/2018</td><td>OW</td><td>123-46562</td><td>Ruegge 3J-4H-N165</td><td>PR</td></tr> <tr><td>454444</td><td>WELL</td><td>PR</td><td>10/27/2018</td><td>OW</td><td>123-46563</td><td>Ruegge 3K-4H-N165</td><td>PR</td></tr> <tr><td>454445</td><td>WELL</td><td>PR</td><td>10/18/2018</td><td>OW</td><td>123-46564</td><td>Ruegge 3O-4H-N165</td><td>PR</td></tr> <tr><td>454446</td><td>WELL</td><td>PR</td><td>11/01/2018</td><td>OW</td><td>123-46565</td><td>Ruegge 3E-4H-N165</td><td>PR</td></tr> <tr><td>454447</td><td>WELL</td><td>PR</td><td>03/01/2022</td><td>OW</td><td>123-46566</td><td>Ruegge 3G-4H-N165</td><td>PR</td></tr> <tr><td>454448</td><td>WELL</td><td>PR</td><td>11/01/2018</td><td>OW</td><td>123-46567</td><td>Ruegge 3M-4H-N165</td><td>PR</td></tr> <tr><td>454449</td><td>WELL</td><td>PR</td><td>11/01/2018</td><td>OW</td><td>123-46568</td><td>Ruegge 3R-4H-N165</td><td>PR</td></tr> <tr><td>454450</td><td>WELL</td><td>PR</td><td>05/01/2022</td><td>OW</td><td>123-46569</td><td>Ruegge 3C-4H-N165</td><td>PR</td></tr> <tr><td>454451</td><td>WELL</td><td>PR</td><td>10/27/2018</td><td>OW</td><td>123-46570</td><td>Ruegge 3F-4H-N165</td><td>PR</td></tr> <tr><td>454452</td><td>WELL</td><td>PR</td><td>10/18/2018</td><td>OW</td><td>123-46571</td><td>Ruegge 3N-4H-N165</td><td>PR</td></tr> </tbody> </table>							Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	426712	WELL	PR	08/01/2019	OW	123-34764	STELLING 3A-4H	PR	428575	WELL	PR	02/01/2019	OW	123-35413	STELLING 3B-4H	PR	454437	WELL	PR	10/29/2018	OW	123-46556	Ruegge 3D-4H-N165	PR	454438	WELL	SI	05/01/2022	OW	123-46557	Ruegge 3P-4H-N165	SI	454439	WELL	PR	11/01/2018	OW	123-46558	Ruegge 3H-4H-N165	PR	454440	WELL	PR	10/27/2018	OW	123-46559	Ruegge 3I-4H-N165	PR	454441	WELL	PR	10/11/2018	OW	123-46560	Ruegge 3Q-4H-N165	PR	454442	WELL	PR	10/30/2018	OW	123-46561	Ruegge 3L-4H-N165	PR	454443	WELL	PR	11/01/2018	OW	123-46562	Ruegge 3J-4H-N165	PR	454444	WELL	PR	10/27/2018	OW	123-46563	Ruegge 3K-4H-N165	PR	454445	WELL	PR	10/18/2018	OW	123-46564	Ruegge 3O-4H-N165	PR	454446	WELL	PR	11/01/2018	OW	123-46565	Ruegge 3E-4H-N165	PR	454447	WELL	PR	03/01/2022	OW	123-46566	Ruegge 3G-4H-N165	PR	454448	WELL	PR	11/01/2018	OW	123-46567	Ruegge 3M-4H-N165	PR	454449	WELL	PR	11/01/2018	OW	123-46568	Ruegge 3R-4H-N165	PR	454450	WELL	PR	05/01/2022	OW	123-46569	Ruegge 3C-4H-N165	PR	454451	WELL	PR	10/27/2018	OW	123-46570	Ruegge 3F-4H-N165	PR	454452	WELL	PR	10/18/2018	OW	123-46571	Ruegge 3N-4H-N165	PR
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status																																																																																																																																																							
426712	WELL	PR	08/01/2019	OW	123-34764	STELLING 3A-4H	PR																																																																																																																																																							
428575	WELL	PR	02/01/2019	OW	123-35413	STELLING 3B-4H	PR																																																																																																																																																							
454437	WELL	PR	10/29/2018	OW	123-46556	Ruegge 3D-4H-N165	PR																																																																																																																																																							
454438	WELL	SI	05/01/2022	OW	123-46557	Ruegge 3P-4H-N165	SI																																																																																																																																																							
454439	WELL	PR	11/01/2018	OW	123-46558	Ruegge 3H-4H-N165	PR																																																																																																																																																							
454440	WELL	PR	10/27/2018	OW	123-46559	Ruegge 3I-4H-N165	PR																																																																																																																																																							
454441	WELL	PR	10/11/2018	OW	123-46560	Ruegge 3Q-4H-N165	PR																																																																																																																																																							
454442	WELL	PR	10/30/2018	OW	123-46561	Ruegge 3L-4H-N165	PR																																																																																																																																																							
454443	WELL	PR	11/01/2018	OW	123-46562	Ruegge 3J-4H-N165	PR																																																																																																																																																							
454444	WELL	PR	10/27/2018	OW	123-46563	Ruegge 3K-4H-N165	PR																																																																																																																																																							
454445	WELL	PR	10/18/2018	OW	123-46564	Ruegge 3O-4H-N165	PR																																																																																																																																																							
454446	WELL	PR	11/01/2018	OW	123-46565	Ruegge 3E-4H-N165	PR																																																																																																																																																							
454447	WELL	PR	03/01/2022	OW	123-46566	Ruegge 3G-4H-N165	PR																																																																																																																																																							
454448	WELL	PR	11/01/2018	OW	123-46567	Ruegge 3M-4H-N165	PR																																																																																																																																																							
454449	WELL	PR	11/01/2018	OW	123-46568	Ruegge 3R-4H-N165	PR																																																																																																																																																							
454450	WELL	PR	05/01/2022	OW	123-46569	Ruegge 3C-4H-N165	PR																																																																																																																																																							
454451	WELL	PR	10/27/2018	OW	123-46570	Ruegge 3F-4H-N165	PR																																																																																																																																																							
454452	WELL	PR	10/18/2018	OW	123-46571	Ruegge 3N-4H-N165	PR																																																																																																																																																							
General Comment: <div style="height: 40px; border: 1px solid black;"></div>																																																																																																																																																														

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>

Flaring:

Type	<input type="text"/>	
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: <input type="text"/>

Inspected Facilities

Facility ID: 426712 Type: WELL API Number: 123-34764 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 03/21/2022 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 428575 Type: WELL API Number: 123-35413 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 03/21/2022 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 454437 Type: WELL API Number: 123-46556 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 05/02/2022 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 454438 Type: WELL API Number: 123-46557 Status: SI Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: EQUIPMENT ONSITE

Comment: SI

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 02/28/2022

Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 317

Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 454439

Type: WELL

API Number: 123-46558

Status: PR

Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 05/02/2022

Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0

Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 454440

Type: WELL

API Number: 123-46559

Status: PR

Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 05/02/2022

Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0

Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 454441

Type: WELL

API Number: 123-46560

Status: PR

Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 05/02/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Workover

Comment: This is a Brigade workover rig. At time of inspection crew was cleaning out hole.

Corrective Action:

Date:

Facility ID: 454442 Type: WELL API Number: 123-46561 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 05/02/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 12 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 454443 Type: WELL API Number: 123-46562 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 05/02/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 454444 Type: WELL API Number: 123-46563 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 05/02/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 454445 Type: WELL API Number: 123-46564 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 08/23/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 45 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 454446 Type: WELL API Number: 123-46565 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 05/02/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 454447 Type: WELL API Number: 123-46566 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 05/02/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 454448	Type: WELL	API Number: 123-46567	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 05/02/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 454449	Type: WELL	API Number: 123-46568	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 05/02/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 454450	Type: WELL	API Number: 123-46569	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 05/02/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 454451	Type: WELL	API Number: 123-46570	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 05/02/2022 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: _____End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

Facility ID: 454452 Type: WELL API Number: 123-46571 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action: _____

Date: _____

BradenHeadDate of Last Brhd Test: 05/02/2022 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
Inspection due to odor and traffic complaint. At time of inspection crew was cleaning out hole. I did not observe any unusual odor or traffic . It also appears all corrective actions for doc#699503138 have been addressed.	silverr	07/26/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693507575	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5813101