

Inspection Photos

API: 095-06061

Operator: J W OPERATING COMPANY

Inspection Date: 7/20/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 095-06061 | Date: 7/20/2022

Inspection Photos



Photo 1. Drone aerial photo facing southeast toward the location. A perimeter fence remains around the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 095-06061 | Date: 7/20/2022

Inspection Photos



Photo 2. Drone aerial photo facing southeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 095-06061 | Date: 7/20/2022