

Inspection Photos

API: 125-07615

Operator: J W OPERATING COMPANY

Inspection Date: 7/20/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos



Photo 1. Facing north at the location. A uniform crop has been re-established.



Inspection Photos



Photo 2. Facing south at the location. A uniform crop has been re-established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-07615 | Date: 7/20/2022