



99999999

OIL & GAS CONSERVATION COMMISSION  
FIELD INSPECTION REPORT

- ☐ NOTICE OF UNSATISFACTORY INSPECTION  
☒ NOTICE OF SATISFACTORY INSPECTION

1120 Lincoln Street, Suite 801  
Denver, CO 80203  
(303)894-2100

API No. 05-	001 - 07843	LEASE NAME:	Carlson I												
LOCATION:	NENW 22-35: 61W	OPERATOR:	Arlian												
DATE:	12-13-96	INSPECTOR:	EBB												
Insp. Type:	SR	Insp. Status:	PA	PA:	Y	N	Pass/Fail:	P	F	Viol.:	Y	N	NOV:	Y	N

INSPECTION ITEM	COMMENTS	INPUT
<b>Well ID Signs</b> (Rule 210, 604.c(4))		
<b>Pits (Reserve/Production)</b> (Rule 902, 903, 904, 905)		
<b>Fences</b> (Rule 603.b.7, 604.C.(3), 1002.A)		
<b>Tank Battery Equipment</b> (Rule 603.b.3, 604)		
<b>Fire Walls/Berms/Dikes</b> (Rule 603.b.12, 604)		
<b>General Housekeeping</b> (Rule 603)		
<b>Spills (Oil/Water)</b> (Rule 907)		
<b>Bradenhead</b> (Rule 207.b)		
<b>Drilling Well/Workover</b> (Rule 317)		
<b>Surface Rehabilitation</b> (Rule 1002, 1003, 1004, 1103)		
<b>Miscellaneous</b>	pipe removed, field plowed and planted.	✓

## CORRECTIVE ACTION REQUIRED:

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.