

# Construction and Stormwater Inspection

July 13, 2022

Operator: EXTRACTION OIL & GAS INC- #10459

Location ID: 460669

Inspection Document #: 697504069

Weld County, CO

NWSW Section 18 T2N R68W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation**  
**Commission**

Department of Natural Resources



**Photo 1.** Drone imagery from 6/9/2022 illustrates the central-southern location during active construction operations. Topsoil has been stockpiled along the southern perimeter of location. Photo also illustrates the perimeter ditch and berm BMP.



Inspection Photos  
Location Name: Blue Paintbrush /Facility  
Location ID: 460669



**Photo 2.** Drone imagery from 6/9/2022 illustrates the central-northern location during active construction operations.





**Photo 3.** Drone imagery from 6/17/2022 illustrates the central-southern location during active construction operations.





**Photo 4.** Drone imagery from 6/17/2022 illustrates the central-northern location during active construction operations.





**Photo 5.** Drone imagery from 7/13/2022 illustrates the central-southern location during active construction operations.





**Photo 6.** Drone imagery from 7/13/2022 illustrates the central-northern location during active construction operations.



Inspection Photos  
Location Name: Blue Paintbrush /Facility  
Location ID: 460669



**Photo 7.** Photo taken from the northeastern location, facing Northeast. Photo illustrates a sediment trap BMP with a temporarily stabilized outlet.



**Photo 8.** Photo taken from the northern location, facing South. Photo illustrates there appears to be a retention area being constructed for the final stormwater BMPs.