

# Inspection Photos

API: 017-07741

Operator: PRONGHORN OPERATING LLC

Inspection Date: 7/22/2022



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 017-07741 | Date: 7/22/2022

## Inspection Photos



**Photo 1.** Facing east toward the location. There are areas of the location that have no sign of crop growth and there are undesirable weeds.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07741 | Date: 7/22/2022



## Inspection Photos



**Photo 2.** Facing north toward the location. There are areas of the location that have no sign of crop growth and there are undesirable weeds.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07741 | Date: 7/22/2022

## Inspection Photos



**Photo 3.** Facing west toward the location. There are areas of the location that have no sign of crop growth and there are undesirable weeds.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07741 | Date: 7/22/2022



## Inspection Photos



**Photo 4.** Facing northwest toward the surrounding undisturbed crop field.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07741 | Date: 7/22/2022