



Inspection Photos

location 458790

Spill 482603

Inspection Date: 7/25/2022

All Photos taken by Kris Neidel

Photo #1 secondary containment at triplex pump where spill originated.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

location 458790

Spill 482603

Inspection Date: 7/25/2022

All Photos taken by Kris Neidel



Photo #2 photo is showing secondary containment of triplex pump, it appeared that some black staining was below the secondary containment. The source of the staining is not conclusive by observation.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos

location 458790

Spill 482603

Inspection Date: 7/25/2022

All Photos taken by Kris Neidel

Photo #3 fluid inside secondary containment.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

location 458790

Spill 482603

Inspection Date: 7/25/2022

All Photos taken by Kris Neidel



Photo #4 looking west, note dark spot is where spray/spill occurred.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos
location 458790
Spill 482603
Inspection Date: 7/25/2022
All Photos taken by Kris Neidel

Photo #5 close up of photo #4

Inspection Photos

location 458790

Spill 482603

Inspection Date: 7/25/2022

All Photos taken by Kris Neidel



Photo #6 triplex building where spill occurred.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

location 458790

Spill 482603

Inspection Date: 7/25/2022

All Photos taken by Kris Neidel



Photo #7 dark shading in background is where oil sprayed off location onto fill slope.

Inspection Photos

location 458790

Spill 482603

Inspection Date: 7/25/2022

All Photos taken by Kris Neidel



Photo #8 tan shaded gravel is where oil sprayed off pad.



Inspection Photos

location 458790

Spill 482603

Inspection Date: 7/25/2022

All Photos taken by Kris Neidel



Photo #9 sprayed oil accumulated on vegetation off the pad on fill slope.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

location 458790

Spill 482603

Inspection Date: 7/25/2022

All Photos taken by Kris Neidel



Photo #10 close up of vegetation where oil accumulated. This is off pad on fill slope



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

location 458790

Spill 482603

Inspection Date: 7/25/2022

All Photos taken by Kris Neidel



Photo #



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

location 458790

Spill 482603

Inspection Date: 7/25/2022

All Photos taken by Kris Neidel



Photo #12 close up of vegetation where oil accumulated. This is off pad on fill slope



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

location 458790

Spill 482603

Inspection Date: 7/25/2022

All Photos taken by Kris Neidel



Photo #13 close up of vegetation where oil accumulated. This is off pad on fill slope



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources