

Interim Reclamation Inspection

July 16 & 17, 2022

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 323207

Inspection Document #: 697504071

Weld County, CO

NESE Section 9 T1N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources



Photo 1. Google Earth aerial imagery from 10/9/2015 during active operations illustrating the subject location.



Inspection Photos

Location Name: CHAMPLIN 86 AMOCO I #1

Location ID: 323207



Photo 2. COGCC Drone aerial imagery from July 16, 2022 overlaid onto Google Earth. This imagery is illustrating the current vegetation, which will be referenced again in Photo #4.





Photo 3. Google Earth aerial imagery from 10/9/2015 with data (blue line) that was collected on July 16, 2022. The blue polygon illustrates where flood irrigation was occurring and it appears the western location is too high and impacted vegetation off location.





Photo 4. COGCC Drone aerial imagery from July 16, 2022 overlaid with the blue polygon. This image is illustrating that area of vegetation that appears to be impacted due to the location not being properly contoured.

Inspection Photos
Location Name: CHAMPLIN 86 AMOCO I #1
Location ID: 323207



Photo 5. Photo taken from the western location, facing East. Photo illustrates an area that appears to be higher in elevation that appears to be impacted vegetation off location.



Photo 6. Photo taken from the previous photo location, facing Northwest. Photo illustrates the approximate ¼ acre area that appears to be impacted due to a contouring issue along the western location.