

**KP KAUFFMAN COMPANY INC
MCCALLUM UNIT-69N79W 13NENE
Location # 324742**



Well sign missing API# and The public road used to access the Well.



Weeds growing around pump jack. Oil stained ground at pumpjack.

KP KAUFFMAN COMPANY INC
MCCALLUM UNIT-69N79W 13NENE
Location # 324742



Oil stained ground at pumpjack.



Oil stained ground at well.

KP KAUFFMAN COMPANY INC
MCCALLUM UNIT-69N79W 13NENE
Location # 324742



Oil stained ground at pumpjack.

**KP KAUFFMAN COMPANY INC
MCCALLUM UNIT-69N79W 13NENE
Location # 324742**



Deadman marker needs repaired



Deadman marker needs repaired