

Inspection Photos

July 26, 2022

Operator: SWN Production Company LLC - #10396

Location ID: 313256

Location Name: Brown-66N92W /8NENW

Inspection Document #: 702800492

Moffat County, CO

NENW Section 8 T6N R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Brown-66N92W /8NENW
Location ID: 313256



Photo 1. Photo taken from the center of the Location shows the Location sign.



Photo 2. Photo taken from the north, at the Location entrance shows an overview of the Location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800492

Inspection Photos
Location Name: Brown-66N92W /8NENW
Location ID: 313256



Photo 3. Photo taken from the west of the Location shows the fill slope of the Location. The Location must be recontoured/regraded.



Photo 4. Photo taken from the southwest of the Location shows the transition from the undisturbed area (foreground) to the Location. Photo shows cut and fill slopes within the red circle. The Location must be recontoured/regraded.

Inspection Photos
Location Name: Brown-66N92W /8NENW
Location ID: 313256



Photo 5. Photo taken from the east of the Location shows the cut slope (foreground) has been seeded with crested wheatgrass, a non-native species which is not found in adjacent reference areas.



Inspection Photos
Location Name: Brown-66N92W /8NENW
Location ID: 313256



Photo 6. Photo taken from the south of the Location shows the reference area vegetation community is native rangeland.

