

# Inspection Photos

API: 071-06550

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 7/28/2022



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-06550 | Date: 7/28/2022

## Inspection Photos



**Photo 1.** Facing south along the access road. There are areas where stormwater is pooling on the road causing widening of the road. This area needs additional stabilization.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06550 | Date: 7/28/2022

## Inspection Photos



**Photo 2.** Facing south along the access road. There are areas where stormwater is pooling on the road causing widening of the road. This area needs additional stabilization.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06550 | Date: 7/28/2022



## Inspection Photos



**Photo 3.** Facing south toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06550 | Date: 7/28/2022

## Inspection Photos



**Photo 4.** Well sign is posted.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06550 | Date: 7/28/2022



## Inspection Photos



**Photo 5.** Facing south just past the location along the access road. There are areas where stormwater is pooling on the road causing widening of the road. This area needs additional stabilization.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06550 | Date: 7/28/2022