

# Inspection Photos

Loc: 309334

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 7/28/2022



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc# 309334 | Date: 7/28/2022

## Inspection Photos



**Photo 1.** Facing south along the access road. There are areas where stormwater is pooling on the road causing widening of the road. This area needs additional stabilization. Approximate Lat/Long:37.23652,-104.69804



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc# 309334 | Date: 7/28/2022

## Inspection Photos



**Photo 2.** Facing south along the access road. There are areas where stormwater is pooling on the road causing widening of the road. This area needs additional stabilization. Approximate Lat/Long:37.24515,-104.68856



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc# 309334 | Date: 7/28/2022

Inspection Photos



**Photo 3.** Approximate Lat/Long:37.246320,-104.679854



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc# 309334 | Date: 7/28/2022