

Inspection Photos

July 26, 2022

Operator: SWN Production Company LLC - #10396

Location ID: 313257

Location Name: Bull-66N92W /8NWNW

Inspection Document #: 702800497

Moffat County, CO

NWNW Section 8 T6N R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Bull-66N92W /8NWNW
Location ID: 313257



Photo 1. Photo taken from the center of the Location shows the Location sign.



Photo 2. Photo taken from the north, at the Location entrance shows an overview of the Location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800497

Inspection Photos
Location Name: Bull-66N92W /8NWNW
Location ID: 313257



Photo 3. Photo taken from the north of the Location shows the cut slope of the Location. The Location must be recontoured/regraded for final reclamation.



Photo 4. Photo taken from the north of the Location shows the fill slope of the Location. The Location must be recontoured/regraded for final reclamation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800497

Inspection Photos
Location Name: Bull-66N92W /8NWNW
Location ID: 313257



Photo 5. Photo taken from the northwest of the Location shows houndstongue, a CO List B Noxious Weed.



Photo 6. Photo taken from the southeast of the Location shows whitetop, a CO List B Noxious Weed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800497

Inspection Photos
Location Name: Bull-66N92W /8NWNW
Location ID: 313257



Photo 7. Photo taken from the southeast of the Location shows Scotch thistle, a CO List B Noxious Weed.




Photo 8. Photo taken from the southeast of the Location shows Russian knapweed, a CO List B Noxious Weed.



Inspection Photos
Location Name: Bull-66N92W /8NWNW
Location ID: 313257



Photo 9. Photo taken from the northwest of the Location shows cement waste has been discharged on Location.



Photo 10. Photo taken from the south of the Location shows cement waste has been discharged on Location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800497