

Inspection Photos

July 26, 2022

Operator: SWN Production Company LLC - #10396

Location ID: 313258

Location Name: Cutthroat-66N92W /8SWNW

Inspection Document #: 702800499

Moffat County, CO

SWNW Section 8 T6N R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Cutthroat-66N92W /8SWNW
Location ID: 313258



Photo 1. Photo taken from the west, at the Location entrance shows an overview of the Location.



Inspection Photos
Location Name: Cutthroat-66N92W /8SWNW
Location ID: 313258



Photo 2. Photo taken from the center of the Location shows Scotch thistle, a CO List B Noxious Weed.



Photo 3. Photo taken from the southeast of the Location shows whitetop, a CO List B Noxious Weed.



Inspection Photos

Location Name: Cutthroat-66N92W /8SWNW

Location ID: 313258



Photo 4. Photo taken from the northwest of the Location shows cement waste has been discharged on Location and off Location resulting in offsite degradation.



Photo 5. Photo taken from the northwest of the Location shows cement waste covering the soil surface.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800499