

Inspection Photos

July 26, 2022

Operator: SWN Production Company LLC - #10396

Location ID: 313259

Location Name: Rainbow-66N92W /7NENE

Inspection Document #: 702800501

Moffat County, CO

NENE Section 7 T6N R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Rainbow-66N92W /7NENE
Location ID: 313259



Photo 1. Photo taken from the center of the Location shows the Location sign.



Photo 2. Photo taken from the north, at the Location entrance shows an overview of the Location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800501

Inspection Photos
Location Name: Rainbow-66N92W /7NENE
Location ID: 313259



Photo 3. Photo taken from the west of the Location Russian knapweed, a CO List B Noxious Weed.



Photo 4. Photo taken from the fill slope at the east of the Location shows scotch thistle, a CO List B Noxious Weed.

Inspection Photos
Location Name: Rainbow-66N92W /7NENE
Location ID: 313259



Photo 5. Photo taken from the north of the Location shows the reference area vegetation community to the north, west and south is crop land.



Photo 6. Photo taken from the east of the Location shows the reference area vegetation community to the east is native rangeland.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800501