

Inspection Photos and Issue Report

7/27/2022

Operator: CAERUS PICEANCE LLC # 10456

Location #479214

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location #479214



Photo 1: Photo taken from the perimeter stormwater ditch. Photo example showing topsoil (yellow arrow) in use as part of stormwater controls (ditch/berm) to manage runoff on the Location.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location #479214



Photo 2: Photos examples showing topsoil remains in use as part of the Locations perimeter stormwater controls, specifically.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location #479214



Photo 3: Photos examples showing topsoil remains in use as part of the Locations perimeter stormwater controls, specifically, the sediment trap on the east end of the Location. Photo also shows control has not been constructed with an engineered outlet to allow for proper stormwater discharge.