


COLORADO OIL



99999999

ON COMMISSION  
RT

WM



1120 Lincoln Street, Suite 801  
Denver, CO 80203  
(303)894-2100

NOTICE OF UNSATISFACTORY INSPECTION

NOTICE OF SATISFACTORY INSPECTION

API No. 05- 001 - 6366

LEASE NAME: Poncho TSWD - 4

LOCATION: 32SE 34-3S-59W

OPERATOR: Poncho Prod

DATE: 5-21-97

INSPECTOR: EBB

Insp. Type: SR Insp. Status: PA PA:  Y  N Pass/Fail:  P  F Viol.: Y  N  Y NOV: Y  N  Y

INSPECTION ITEM

COMMENTS

INPUT

<b>Well ID Signs</b> (Rule 210, 604.c(4))		
<b>Pits (Reserve/Production)</b> (Rule 902, 903, 904, 905)		
<b>Fences</b> (Rule 603.b.7, 604.C.(3), 1002.A)		
<b>Tank Battery Equipment</b> (Rule 603.b.3, 604)		
<b>Fire Walls/Berms/Dikes</b> (Rule 603.b.12, 604)		<b>COGCC</b> <b>JUL 10 97</b>
<b>General Housekeeping</b> (Rule 603)		
<b>Spills (Oil/Water)</b> (Rule 907)		
<b>Bradenhead</b> (Rule 207.b)		
<b>Drilling Well/Workover</b> (Rule 317)		
<b>Surface Rehabilitation</b> (Rule 1002, 1003, 1004, 1103)	<u>grassed over site.</u>	
<b>Miscellaneous</b>		

RECEIVED

**CORRECTIVE ACTION REQUIRED:**

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.



00416704

Site