

Inspection Photos

July 26, 2022

Operator: SWN Production Company LLC - #10396

Location ID: 311776

Location Name: Brook-66N92W /5SWSW

Inspection Document #: 702800503

Moffat County, CO

SWSW Section 5 T6N R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Brook-66N92W /5SWSW
Location ID: 311776



Photo 1. Photo taken from the center of the Location shows the Location sign.



Photo 2. Photo taken from the south, at the Location entrance shows an overview of the Location.



Inspection Photos
Location Name: Brook-66N92W /5SWSW
Location ID: 311776



Photo 3. Photo taken from the west of the Location shows the cut slope of the Location. The Location must be recontoured/regraded for final reclamation.



Photo 4. Photo taken from the east of the Location shows the fill slope of the Location. The Location must be recontoured/regraded for final reclamation. Photo also shows a large infestation of Russian knapweed, a CO list B Noxious Weed.

Inspection Photos
Location Name: Brook-66N92W /5SWSW
Location ID: 311776



Photo 5. Photo taken from the east of the Location shows a berm which is densely covered in noxious weeds, including cheatgrass, mullein (List C) and scotch thistle (List B) shown in photo. Recontouring/regrading is required for final reclamation



Photo 6. Refer to Photo 5 comment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800503

Inspection Photos
Location Name: Brook-66N92W /5SWSW
Location ID: 311776



Photo 7. Photo taken from the north of the Location shows Scotch thistle, a CO List B Noxious Weed.



Photo 8. Photo taken from the center of the Location shows Scotch thistle, a CO List B Noxious Weed.

Inspection Photos
Location Name: Brook-66N92W /5SWSW
Location ID: 311776



Photo 9. Photo taken from the northwest of the Location shows where cement waste has been discharged on Location.



Photo 10. Refer to Photo 9 comment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800503

Inspection Photos
Location Name: Brook-66N92W /5SWSW
Location ID: 311776



Photo 11. Photo taken from the north of the Location shows the reference area vegetation is crop land.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800503