

Inspection Photos

API: 071-08769

Operator: WAPITI OPERATING LLC

Inspection Date: 8/1/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08769 | Date: 8/1/2022

Inspection Photos



Photo 1. This culvert inlet was cleaned out however, the culvert is full of sediment. Previous corrective action was not completed. Lat/Long:37.00581,-104.83861.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08769 | Date: 8/1/2022

Inspection Photos



Photo 2. There is an erosion gully along the road that needs to be repaired and stabilized. Previous corrective action was not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08769 | Date: 8/1/2022

Inspection Photos



Photo 3. The side of the road is eroded and not stabilized. Erosion head cutting is continuing to occur further back. This area needs to be repaired and stabilized. Previous corrective action not completed. Red arrow points to 4.5 ft. shovel. Lat/Long:36.99952,-104.83425. There are also noxious shown in the photo.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08769 | Date: 8/1/2022

Inspection Photos



Photo 4. There are noxious weeds along the access road that are wilted from recent weed control. Canada thistle is shown wilted in the photo.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08769 | Date: 8/1/2022

Inspection Photos



Photo 5. This culvert inlet was cleaned out however, the culvert is full of sediment which needs to be cleaned out. Lat/Long:36.99405,-104.84710.

Previous corrective action not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08769 | Date: 8/1/2022

Inspection Photos



Photo 6. Facing northeast toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08769 | Date: 8/1/2022

Inspection Photos




Photo 7. There are noxious weeds Hounds tongue which has not been controlled. The noxious weeds have already produced seed so the weeds will now need to be bagged and removed. Previous corrective action not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08769 | Date: 8/1/2022