

Inspection Photos

Location Name: PEPPLER-66N63W /17SWNW

Location #: 310651



Photo #1

Peppler 17-12 (05-123-26749) Wellsite

Shut-In | SI



Photo #2

Peppler 17-12, 17-22 Battery site

Shut-down | Inactive

Inspection Photos
Location Name: PEPPLER-66N63W /17SWNW
Location #: 310651



Photo #3
Peppler 17-12, 17-22 Battery site
Shut-down | Inactive
Tank(s): SE corner



Photo #4
Peppler 17-12, 17-22 Battery site
Shut-down | Inactive
Separator, ECD

Inspection Photos

Location Name: PEPPLER-66N63W /17SWNW

Location #: 310651



Photo #5

Peppler 17-12, 17-22 Battery site

Shut-down | Inactive

Battery sign



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources