

Inspection Photos
Location Name: PEPPLER-66N63W /17SENW
Location #: 310057



Photo #1
Peppler 17-22 (05-123-25817) Wellsite
Shut-In | SI



Photo #2
Peppler 17-12, 17-22 Battery site
Shut-down | Inactive
Reference: Loc. #310651 for Battery info