

Inspection Photos

Location Name: PEPPLER PC /AA17-20 /17NESE

Location #: 419494



Photo #1

Peppler PC AA17-20 (05-123-32266) Wellsite

Temporarily Abandoned | TA



Photo #2

**Bashor PC AA17-21, 17-13, 17-15, 17-16, 17-22, 17-23,
17-24, 17-41, Peppler PC AA17-20 Battery site**

Abandoned: ALL Equipment removed

Formerly served:

Bashor 17-42 ; Plugged & Abandoned | PA