



**Photo 1:** View of release point and eastern portion of spill pathway. (7/24/22)



**Photo 2:** View of release from the west side of the spill pathway looking east. (7/24/22)



**Photo 3:**  
View of the western extent of spill pathway. (7/24/22)



**Photo 4:**  
View of area west of release point and former pooling area on the access road observed in **Photo 1**. Looking northeast with the release point in the background. (7/26/22)



**Photo 5:**  
View of spill pathway area and release point located in the foreground on the right side of the photograph. Looking west along the access road from approximately 15-feet east of the release point. (7/26/22)



**Photo 6:**  
View of possible oil dispersal/misting northwest of the release point, Area is between the electrical lines and earthen berm. Looking west with sample location O\_24\_@ 0". (7/26/22)



**Photo 7:**  
View of possible oil dispersal/misting deposition northwest of the release point. View is looking northwest from the top of the earthen berm. (7/26/22)