

# Inspection Photos

API: 071-09011

Operator: WAPITI OPERATING LLC

Inspection Date: 8/1/2022



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-09011 | Date: 8/1/2022

## Inspection Photos



**Photo 1.** There are noxious weeds along the access road that need to be controlled. The red arrow points to Houndstongue which is a biennial. The leaves shown are the first year growth and is a good time for control.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09011 | Date: 8/1/2022



## Inspection Photos



**Photo 2.** Facing northwest toward the wellsite.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09011 | Date: 8/1/2022

## Inspection Photos



**Photo 3.** Facing toward the wellhead. The noxious weeds at the wellhead are wilted.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09011 | Date: 8/1/2022