

Inspection Photos
Location Name: USA 21-6
Location ID: 318871



Photo 1 – Tank Battery



Photo 2 – Tank Battery Sign

Inspection Photos
Location Name: USA 21-6
Location ID: 318871



Photo 3 – Water Tank now has Labels



Photo 4 – Heater Treater

Inspection Photos
Location Name: USA 21-6
Location ID: 318871



Photo 5 – Pumping Unit



Photo 6 – Well Sign

Inspection Photos
Location Name: USA 21-6
Location ID: 318871




Photo 7 – Wellhead – Stained Sol




Photo 8 – Wellhead

Inspection Photos
Location Name: USA 21-6
Location ID: 318871



Photo 9 – Pit Area