

Final Reclamation Inspection

Date:07/05/2022

Operator: Texaco Exploration and Production INC-
#86900

Location ID: 393535

Inspection Document #: 696105286

Morgan County, CO

NWNW Section 27 T1N R56W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: PETERSON, MAX #12

Location ID: 393535



Photo 1. Access road photo taken east of location, looking west. Photo illustrates access road has not been recontoured or reshaped.

Inspection Photos

Location Name: PETERSON, MAX #12

Location ID: 393535



Photo 2. Location photo taken from southern portion, facing north. Photo illustrates large areas of non-uniform vegetation cover resulting in bare soil.



Photo 3. Location photo taken from western portion, facing east. See comments in Photo 2.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 696105286

Inspection Photos

Location Name: PETERSON, MAX #12

Location ID: 393535



Photo 4. Location photo taken from northern portion, facing south. See comments in Photo 2.



Photo 5. Location photo taken from eastern portion, facing west. See comments in Photo 2.

Inspection Photos
Location Name PETERSON, MAX #12
Location ID: 393535



Photo 6. Southern access road photo taken south of location, facing north. Large areas of non-uniform vegetation cover resulting in bare soil. Access road has not been reclaimed.



Photo 7. Access roads for location (red line) that have not been reclaimed, and offsite disturbance (green polygon) not reclaimed.

Inspection Photos

Location Name: PETERSON, MAX #12

Location ID: 393535



Photo 8. Reference area photo taken east of location, facing north. Reference area illustrates uniform plant cover of native species (e.g. sand drop seed, buffalo grass, sand sage).