

Final Reclamation Inspection

Date:07/05/2022

Operator: WESTERN OPERATING COMPANY-95620

Location ID: 313653

Inspection Document #: 696105289

Morgan County, CO

SWNW Section 27 T1N R56W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Sand River #7

Location ID: 313653



Photo 1. Access road photo taken east of location, facing west. Access road has not been reclaimed and shows signs of erosion (highlighted in red).

Inspection Photos
Location Name: Sand River #7
Location ID: 313653



Photo 2. Location photo taken from northern portion, facing south. Subsidence (highlighted in red) observed around well location and non-uniform vegetation cover resulting in bare soil.

Inspection Photos
Location Name: Sand River #7
Location ID: 313653



Photo 3. Location photo taken from eastern portion, facing west. Subsidence (highlighted in red) observed around well location and non-uniform vegetation cover resulting in bare soil.

Inspection Photos
Location Name: Sand River #7
Location ID: 313653



Photo 4. Location photo taken from southern portion, facing north. Subsidence (highlighted in red) observed around well location and non-uniform vegetation cover resulting in bare soil.

Inspection Photos
Location Name: Sand River #7
Location ID: 313653



Photo 5. Location photo taken from western portion, facing east. Subsidence (highlighted in red) observed around well location and non-uniform vegetation cover resulting in bare soil.

Inspection Photos
Location Name: Sand River #7
Location ID: 313653



Photo 6. Reference area photo taken west of location, facing north.

Inspection Photos

Location Name: Sand River #7

Location ID: 313653



Photo 7. Photo illustrates close up of subsided well location and bare soil with some weedy vegetation in foreground (kochia). Photo taken on western portion of location, facing east.