

Final Reclamation Inspection

Date:07/05/2022

Operator: WESTERN OPERATING COMPANY-95620

Location ID: 313649

Inspection Document #: 696105292

Morgan County, CO

NESW Section 27 T1N R56W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: SAND RIVER UNIT 9

Location ID: 313649



Photo 1. Access road photo taken north of location, facing south. Access road has not been reclaimed (e.g. not recontoured or regraded).

Inspection Photos

Location Name: SAND RIVER UNIT 9

Location ID: 313649



Photo 2. Well location photo taken from the southern portion, facing north. Non-uniform vegetation cover resulting in bare soil and weedy vegetation.

Inspection Photos

Location Name: SAND RIVER UNIT 9

Location ID: 313649



Photo 3. Well location photo taken from eastern portion, facing west; bare soil and weedy vegetation present.



Photo 4. Well location photo taken from western portion, facing east; bare soil and weedy vegetation present.

Inspection Photos

Location Name: SAND RIVER UNIT 9

Location ID: 313649



Photo 5. Access road photo taken on northern portion of location, facing north. Road has not be recontoured or regraded. Unidentified pipe marker seen in foreground.