

# Final Reclamation Inspection

Date:07/05/2022

Operator: WESTERN OPERATING COMPANY-95620

Location ID: 313656

Inspection Document #: 696105293

Morgan County, CO

SWNE Section 27 T1N R56W

Dylan Edwardson  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**


Department of Natural Resources

Inspection Photos  
Location Name: Sand River Unit #4  
Location ID: 313656



**Photo 1.** Photo taken south of location, facing north. Access road has not been reclaimed (e.g. recontoured, regraded, revegetated).

Inspection Photos  
Location Name: Sand River Unit #4  
Location ID: 313656



**Photo 2.** Location photo taken from western portion, facing east. Debris (pipe fittings, concrete cores) left on site.



**Photo 3.** Location photo taken from northern portion, facing south. Non-uniform vegetation cover resulting in bare soil.

Inspection Photos  
Location Name: Sand River Unit #4  
Location ID: 313656



**Photo 4.** Location photo taken from eastern portion, facing west. Debris observed on location.



**Photo 5.** Location photo taken from southern portion, facing north. Non-uniform vegetation cover resulting in bare soil.