

Final Reclamation Inspection

Date: 07/05/2022

Operator: NOBLE ENERGY INC-100322

Location ID: 393534

Inspection Document #: 696105295

Morgan County, CO

NWNE Section 27 T1N R56W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: SAND RIVER #3

Location ID: 393534



Photo 1. Access road photo taken from east entrance, facing west. Road has not been reclaimed.



Photo 2. Location photo taken from southern portion, facing north. Non-uniform vegetation cover resulting in bare soil.



Inspection Photos

Location Name: SAND RIVER #3

Location ID: 393534



Photo 3. Location photo taken from northern portion, facing south. Non-uniform vegetation cover resulting in bare soil.



Photo 4. Location photo taken from western portion, facing east. Non-uniform vegetation cover resulting in bare soil.

Inspection Photos

Location Name: SAND RIVER #3

Location ID: 393534



Photo 5. Well location photo taken from southern portion, facing north. Non-uniform vegetation cover resulting in bare soil.