

Final Reclamation Inspection

Date:07/07/2022

Operator: CRESTONE PEAK RESOURCES OPERATING
LLC-10633

Location ID: 321534

Inspection Document #: 696105297

Broomfield County, CO

NWNW Section 23 T1N R68W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Bury Crandell #22-23
Location ID: 321534



Photo 1. Access road entrance, facing southwest. Photo illustrates presence of weedy vegetation (kochia).

Inspection Photos
Location Name: Bury Crandell #22-23
Location ID: 321534



7/7/22, 11:19 AM
+40.042073, -104.975665
Broomfield, CO 80516

Photo 2. Reclaimed area outlined in red, facing north. Photo illustrates reclaimed area with weedy vegetation (kochia) and List B and C noxious weeds (musk thistle, field bindweed). Area to the right of outline managed by ditch company.

Inspection Photos
Location Name: Bury Crandell #22-23
Location ID: 321534



Photo 3. Reclaimed area photo taken in center of location, facing north. List B and C noxious weeds present (musk thistle, field bindweed) and other annual weedy vegetation.

Inspection Photos
Location Name: Bury Crandell #22-23
Location ID: 321534



Photo 4. Reclaimed area photo taken from center of location, facing south. Weedy vegetation observed.

Inspection Photos
Location Name: Bury Crandell #22-23
Location ID: 321534



Photo 5. Reclaimed area photo taken from center of location, facing south. Non-uniform vegetation cover resulting in bare soil and debris (highlighted in red) observed.