

Interim Reclamation and Stormwater Inspection

Date: 07/26/2022

Operator: MALLARD EXPLORATION LLC- 10670

Location ID: 447902

Inspection Document #: 696105316

Weld County, CO

NENW Section 31 T9N R59W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SHULL FED 31-32-1HN
Location ID: 447902



Photo 1. Location entrance; facing east.

Inspection Photos
Location Name: SHULL FED 31-32-1HN
Location ID: 447902



Photo 2. Photo taken from the southern portion of well pad, facing southeast. Photo illustrates interim reclamation area has been regraded with stabilized soil (straw crimped).

Inspection Photos
Location Name: SHULL FED 31-32-1HN
Location ID: 447902



Photo 3. Dozer parked/stored on location; photo taken from southeast corner of pad, facing southeast.

Inspection Photos
Location Name: SHULL FED 31-32-1HN
Location ID: 447902



Photo 4. Photo taken from the eastern well pad, facing southeast. See comments under Photo 2.

Inspection Photos
Location Name: SHULL FED 31-32-1HN
Location ID: 447902



Photo 5. Photo taken from east portion of pad, facing northeast. See comments under Photo 2.

Inspection Photos
Location Name: SHULL FED 31-32-1HN
Location ID: 447902



Photo 6. Location has been stabilized with road base and fenced off well head.

Inspection Photos
Location Name: SHULL FED 31-32-1HN
Location ID: 447902



Photo 7. Photo taken from center of location, facing northwest. Unused equipment stored on location outside of wellhead enclosure.