

Interim Reclamation and Stormwater Inspection

Date: 07/26/2022

Operator: MALLARD EXPLORATION LLC- 10670

Location ID: 447898

Inspection Document #: 696105318

Weld County, CO

SESW Section 31 T9N R59W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SHULL FED 31-32-3HN
Location ID: 447898



Photo 1. Photo taken from entrance, facing northeast. Weedy vegetation (kochia, russian thistle) observed on interim reclamation area.

Inspection Photos
Location Name: SHULL FED 31-32-3HN
Location ID: 447898



Photo 2. Weedy vegetation (kochia, russian thistle) observed on interim reclamation area. Left side of photo is offsite/reference area, right side is interim area. Photo taken on northern portion, facing east.

Inspection Photos
Location Name: SHULL FED 31-32-3HN
Location ID: 447898



Photo 3. Weedy vegetation (kochia, russian thistle) observed on interim reclamation area. Photo taken on eastern portion, facing south.

Inspection Photos
Location Name: SHULL FED 31-32-3HN
Location ID: 447898



Photo 4. Weedy vegetation (kochia, russian thistle) observed on interim reclamation area with bare soil exposed. Photo taken on eastern portion, facing north.