



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Monument Ridge Pad /
Location ID: 422286



Approximate distance to nearest subdivision.



Approximate distance to complainant residence.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Monument Ridge Pad /

Location ID: 422286



Photo #7342 Predominant wind direction West to East.