

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC YATER PAD /

Location ID: 159652



Photo #7343 from entrance to location.



Photo #7344 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC YATER PAD /

Location ID: 159652



Photo #7345 from entrance to location.



Photo #7347 Loadline open ended.

Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC YATER PAD /
Location ID: 159652



Photo #7348 Unused equipment in tank containment.



Photo #7349 Unused equipment in tank containment.